



BROADMOOR GOLF CLUB

2340 Broadmoor Drive East • Seattle, Washington 98112 • (206) 325-5600 • FAX (206) 325-5607

October 8, 2003

To Whom It May Concern:

Re: Paul Casey, Casey Group Architects

This letter is to recommend to you the work of Paul Casey and the Casey Group Architects. I personally worked with Paul in conjunction with a water intrusion repair project.

The Broadmoor Golf Club clubhouse was damaged through a faulty installation of an exterior finish. To repair, the old exterior was stripped, damaged areas were repaired and a new finish was installed. We, of course, wanted to be sure our building was "fixed" and that the new exterior would be free of water intrusion.

It was a very complex project due to the architectural detail of the building. In order to maintain the architectural integrity of the building, creativity and ingenuity were required. Paul provided excellent leadership and experience in this area. In addition, he worked extremely well in a team environment and did an excellent job of utilizing the feedback of the other construction professionals.

All drawings and requests for information were handled in a very expedient manner. This greatly contributed to a project that was done ahead of schedule and under budget.

Please feel free to call me regarding this reference. I can be contacted at my office (206) 325-5600 or home (206) 323-8145.

Sincerely,
Broadmoor Golf Club

Steve Hall
General Manager